INSPECTION REPORT

Name of Work : CONSTRUCTION OF RCC DRAIN IN 1ST CROSS ROAD AT PRASHANTHANAGAR IN WARD NO 13 SSD

Work Order	:	EE/DD/WO/77/2015-16 Date 24.3.16
Agency	:	SRI B.MUNIRAJU
B.R No & Date	:	108/2016-17, Date: -31-05-2016
Bill Amount	:	Rs.23,11,621/-
Job Code	:	013-15-000003
P.Code	:	P1771
Date of Inspection	:	02/11/2016

The above said work "Construction of RCC Drain in 1st Cross Road At prashanthnagar in ward no 13 SSD was shown to me by the Concerned ward Engineer.

The above said work is inspected by me along with the Concerned ward Engineer.

The work done is satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of work : Construction of RCC Drain in 1st Cross Road at prashanthanagara in Ward No-13 in SSD.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER
PUBLIC WORKS DEPARTMENT

Name of work: Construction of RCC Drain in 1st Cross Road at prashanthanagara in ward NO 13 in SSD

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name:- Construction of Rcc drain in 1st Cross roads at prashanth nagar in ward no. 13 in shettyhalli sub-division.



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು